



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

SUBJECT: SPEEDOMETER EQUIPMENT - ALL MODELS

BULLETIN T-65-7
(Originally issued
as Bulletin T-62-36)


DATE: JANUARY 14, 1965

Speedometer heads are frequently changed for complaints when in fact, other sources are responsible. The fitting of a new instrument only, without rectifying the cause of the failure, will only result in repeated trouble later. The following table of faults and remedies indicates the action recommended for individual complaints.

FAULT	PROBABLE CAUSE	REMEDY
Fluctuating needle	(a) Oil in instrument	1. Replace head. 2. Clean surplus oil from inner cable and lightly lubricate. Use an approved general purpose grease. ON NO ACCOUNT MUST OIL BE USED. 3. Renew oil seal in gearbox speedometer drive gear.
	(b) Incorrect cable run	1. Ensure connecting nuts at both ends are tight. Check that any bend in the cable is not less than 6" radius.

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

SUBJECT: SPEEDOMETER EQUIPMENT - ALL MODELS


BULLETIN T-65-7
(Originally issued
as Bulletin T-62-36)

DATE: JANUARY 14, 1965

FAULT	PROBABLE CAUSE	REMEDY
Complete lack of reading	Damaged or faulty head	1. Change the instrument. 2. Check that the inner cable does not project more than 3/8" from outer cable at the instrument end. A projection in excess of this indicates engagement on the gearbox end. The depth of engagement should be in a minimum of 12/16". Less than this indicates the possibility of foreign matter in the base of the spindle hole which can be cleaned out with a length of wire.
Failure of mileage reading, or trip recorder	Faulty head or faulty instrument.	1. Replace instrument 2. Check for the possibility of oil in the instrument head and proceed as for the fluctuating needle complaint.

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

SUBJECT: SPEEDOMETER EQUIPMENT - ALL MODELS

BULLETIN T-65-7
(Originally issued
as Bulletin T-62-36)

DATE: JANUARY 14, 1965

NOTE: The flexible drive requires careful handling before and during installation. It must not be knocked or bent into coils of less than 12" diameter or forced into any temporary position, which results in permanent setting or kinking of the outer casing.