

TECHNICAL SERVICE BULLETIN

71-C-8

NO.



April 1971

SUBJECT:

Shoulder Harness Recall

MODELS:

GT-6

A few cases have been reported where GT-6 model cars were fitted with the lap type of seat belt instead of the shoulder type of seat belt required by federal safety standards for all passenger cars other than convertibles.

A letter has been sent to all GT-6 owners of record asking that they return to any Triumph dealer to have the belts replaced where necessary free of charge.

Replacement seat belts, part number V539, are available from your distributor.

Schedule Time Allowance

Remove and replace seat belts 00.25 hours.

Use fault code Z100 to identify these claims. A copy of a letter mailed to all owners of record is printed on the reverse side of this bulletin.

NOTE: This recall applies to vehicles sold through dealers located in the following states: Virginia, West Virginia, Maryland, Delaware, New Jersey, Pennsylvania, New York, Connecticut, Rhode Island, Massachusetts, New Hampshire, Vermont, Maine, and Washington D. C. However, cars presented to you for this service should be rectified if sold through any of these dealers.