



TO: All Dealers

BULLETIN #T-61-8

DEPT: Service and Parts

DATE: May 12, 1961

SUBJECT: TRIUMPH HERALD FRONT SEATS

Reports have been received of driver or passenger discomfort due to contact with one of the frame members of the front seats. This mainly occurs due to slight settling of the seat back allowing the occupants to sink sufficiently far into the seat to contact the seat frame member.

This condition can be readily overcome within a matter of a few minutes by suitably bending the lower seat frame bar in question in a rearward direction. This bar will be found to be of light enough gauge to respond to manual pressure. There is no need to remove any of the upholstery covering during this simple operation which, when complete, can make such a tremendous improvement to the seating comfort.


Zone Service Manager

W. T. Yeager

dm