

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

ATTN: SERVICE & PARTS

BULLETIN T-64-13

SUBJECT: BENDIX PUSH-BUTTON RADIO

DATE: MARCH 6, 1964

Your attention is called to the fitting of the current Bendix Push-Button Radio. A number of these have been returned for faulty operation and have been turned down by the Bendix Corp. for the following reasons:

It has been noted the adaptor plate the securing nuts failure of the unit.

that the chrome bezel has been fitted on the wrong side of when fitting the radio into Triumph models; therefore, when are tightened distortion takes place in the radio set causing

Please make sure that when fitting Bendix radios in the future that the instructions inside each kit are thoroughly followed as it clearly shows the correct method of fitting the bezel in position which, of course, is directly on to the radio receiver and then the radio and bezel inserted into the adaptor plate from the rear, then the securing nuts tightened accordingly. When the completed installation is securely in position only a small portion of the chrome bezel can be seen when sitting in the driver's seat.

This is the correct installation and no problem should then be experienced with the radio set. However, we must emphasize that the instructions issued with each set should be thoroughly read and understood on each model as there is a slight variation to fitting.