

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

BULLETIN T-66-10

SUBJECT: STARTER SOLENOID - TR-4A

DATE: FEBRUARY 10, 1966

This bulletin is to advise you that we are still receiving warranty claims stating that the starter solenoid has failed due to gas contamination.

As a reminder, from serial number CT-50000, which represents the TR-4A series, the starter solenoid was moved to a different position on the firewall, making it impossible for gas contamination to take place.

In future, claims submitted for faulty solenoids should not bear instructions claiming gas contamination. If it has failed it is possibly due to internal failure of the contact switches.

In your own interest, please make sure that when filing future claims for failure of this unit that the correct description is made out on the vendor warranty label and the warranty claim form.