

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

BULLETIN T-66-4

SUBJECT: TR-4 AND TR-4A
GROUND STRAP POSITION

DATE: JANUARY 1, 1966

It has been called to our attention that cases of chafing have been found on the ground strap from the engine to the chassis frame located in the forward left hand side of the engine compartment; therefore, to avoid damage to this part or such parts that it may be contacting, it is suggested that it be examined as part of the normal customer maintenance service to determine if this condition does exist. If this strap is found to be rubbing, it may be either bent into a more suitable position or one of the attachment bolts may be loosened to allow its mounting tab to be turned in such a way that the strap will take a new course.