

TECHNICAL SERVICE BULLETIN

NO.

1-A-6



DATE: 12/12/69

BRITISH LEYLAND MOTORS INC.

600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

Accelerator Linkage

MODELS:

GT 6+

Some difficulty has been experienced in obtaining a smooth progressive movement of the accelerator pedal relative to throttle opening on the above model.

An improvement in this condition can be made by removing the connecting rod (part number 149028) which joins the bell crank lever and the carburetor spindle cross shaft, removing one ball and reducing the total length of the rod by $3/8$ ", re-cutting the thread and replacing the ball end to give a dimension of 2.75" to the centers of the ball ends.

The original dimension of the connecting rod was 3.12" to the centers of the ball ends. The new dimension of 2.75" was introduced at approximate commission number KC 55500.

