

Confidential

TECHNICAL SERVICE BULLETIN

NO.

1-A-8



DATE: May 1970

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

TR-6 Distributors

MODELS:

TR-6

The TR-6 Lucas Distributor will in the future contain "Quickafit" type contact breakers as original equipment.

Due to a modification to the distributor base plate reducing the length of the moving contact pivot pin, the latest distributor will not accomodate the two piece contact set, and must be serviced with a "Quickafit" contact breaker assembly.

"Quickafit" contact breaker sets can be used as replacements on early type distributors.