

Confidential

TECHNICAL SERVICE BULLETIN

NO. 1-C-2



TRIUMPH

DATE: February 12, 1969

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

Window Winder Handle

MODELS:

TR-250

Reports from our field staff indicate that the window winder handle assembly part number 621811 has been changed erroneously under warranty when a failure takes place which, of course, is usually a broken knob.

Please note that the knob is available separately under part number 621768.

JP/bs