

Confidential

TECHNICAL SERVICE BULLETIN

NO.

1-C-7



TRIUMPH

DATE: November 1970

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

Heated Back Door Glass

MODELS:

GT-6 +

We would like to remind you that damage can occur to the heated rear door glass for the following reasons:

- A. Scratching off labels.
- B. Wiping the glass with the back of a ringed hand.
- C. Stowing hard or metal objects so that they abrade the glass.
- D. Cleaning with harsh abrasives, etc.

Needless to say, care should be exercised with this item to prevent unnecessary damage to the circuit.