

Confidential

TECHNICAL SERVICE BULLETIN

NO. 1-D-1



TRIUMPH

DATE: February 28, 1969

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:	MODELS:
Rear Gearbox Oil Seals	All Models

If it is necessary to replace a gearbox extension seal, the replacement must be lubricated with SAE 90 hypoid oil to prevent possible charring of the lip during early stages of running.

If an oil leak is excessive at this point and is thought to be due to pressurization of the unit, be sure and check that the breather hole in the gearbox top cover is not blocked.

JP/bs