

Confidential

TECHNICAL SERVICE BULLETIN

NO.

1-D-5

BRITISH



LEYLAND

TRIUMPH

DATE: 8-8-69

BRITISH LEYLAND MOTORS INC.

600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

GEAR BOX 3rd SPEED GEAR

MODELS:

GT 6 & GT 6+

Your attention is drawn to the variation in the Helix Angle on the 3rd speed gear, gear cluster and constant pinion shaft.

The following part numbers have a 35° Helix Angle and may be used for all replacements if used as a complete set.

<u>Part Number</u>	<u>Description</u>
145994	Gear, 3rd Speed (35° Helix Angle)
213526	Constant Pinion Shaft (35° Helix Angle)
213527	Gear Cluster (35° Helix Angle)

The following part numbers have a 30° Helix Angle and may be used for replacement if used as a complete set.

<u>Part Number</u>	<u>Description</u>
132097	Gear, 3rd Speed (30° Helix Angle)
213113	Constant Pinion Shaft (30° Helix Angle)
212993	Gear Cluster (30° Helix Angle)