


TECHNICAL SERVICE BULLETIN

NO.



DATE: MAY 22, 1970

BRITISH LEYLAND MOTORS INC.
 600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT: INTRODUCTION OF TRIUMPH PASSPORT TO SERVICE AND OWNERS' VEHICLE IDENTIFICATION PLATE	MODELS: ALL MODELS
--	---------------------------

Owners' Service Voucher booklets currently supplied have been superseded by the "Passport to Service", supplies now being forwarded by your distributor. Please remove and discard the old type of Service Voucher booklet from all unsold 1970 cars and replace it with the new Passport to Service and use the new type of warranty registration card which it contains.

The warranty registration card (WAR. 46) is, upon sale of the car, to be completed in block capitals or typed to ensure clarity and mailed by Dealers to the Distributor. This will create an owner identification plate, see page 7 of the new book, which will be mailed directly to the owner by the B.L.M. Inc. central warranty registry.

The warranty registration card is a most important document enabling contact to be established speedily in case of need such as recall campaigns etc.. The card is also necessary so that owners will have accurate documentation for warranty and regular service. The cooperation of all is requested to ensure 100% return of warranty registration cards.

A special pocket in the back of the "Passport to Service" is provided to carry the identification plate and Dealers are urged to impress upon owners the importance and convenience to all concerned by having it available at all times.

TRIUMPH



Your passport to service