

TECHNICAL SERVICE BULLETIN

72-A-1

NO.



TRIUMPH

January 1972

SUBJECT:Engine Blocks and Cylinder Head
Gaskets**MODELS:**

All 1972 Models

The cylinder head gasket now locates in recesses in the cylinder bores.

With the cylinder head and gasket removed the recess in the bores may give the impression that the liners have moved. This condition is normal and cylinder blocks should not be replaced unnecessarily.

The part numbers for the new cylinder head gaskets which are not interchangeable with 1971 model gaskets are as follows:

Spitfire Mk. 4 217757

GT 6 Mk. 3 and TR-6 217291