

TECHNICAL SERVICE BULLETIN

NO.

72 B 2



TRIUMPH

April, 1972

SUBJECT:

Alternator Mounting Spacer

MODELS:

Spitfire MK IV

At approximately engine number FK9210, a Lucas 15 A.C.R. Alternator with a revised body was incorporated.

A change to the shape of the casting necessitated a reduction in the external diameter of the spacer (Part No. 147483) to enable the mounting bolt to locate correctly through both end brackets of the alternator.

Should this new alternator be used to replace the earlier type, the spacer, Part No. 147483 must also be used.