

STANDARD-TRIUMPH MOTOR COMPANY, INC.

NORTHEASTERN ZONE



TO: All Dealers

BULLETIN: T-61-29

DEPT: Service and Parts

DATE: November 6, 1961

SUBJECT: HERALD 1200 REAR WHEEL BRAKE CYLINDERS

To increase braking efficiency, the size of the rear wheel brake cylinder has been increased from 5/8" diameter to 3/4" diameter. The part number of the larger cylinder for both right and left hand is 120132.

Should it be necessary to change one of these wheel cylinders, exercise care to ensure that the smaller size is not fitted in error. Both types are identified by the figures 5/8" or 3/4" moulded in the cylinder casting.

This alteration was introduced from the following Commission Numbers:

GA-15031	- Sedan and Convertible
GA-18360-CP	- Coupe (Not generally imported into the U.S.A.)
G-65719-SP	- Estate Car (not generally imported into the U.S.A.)

NOTE: These instructions are for information only and do not constitute an authority to carry out modifications at the expense of the Standard-Triumph Motor Company, Inc.

W. T. Yeager
Zone Service Manager

W. T. Yeager

dm

Register