



TO: All Dealers

BULLETIN #T-61-30

DEPT: Service and Parts

DATE: November 6, 1961

SUBJECT: HERALD RACK AND PINION STEERING ASSEMBLY

Steering units employing a nut and shim adjustment for controlling the uplift of the steering rack supersede, for production vehicles and spares replacements, earlier units which incorporated a Belleville washer and circlip (Refer T-60-47).

The new unit, which was incorporated at the following Commission Numbers:

GA-8705-LDL Herald 1200 Sedan

GA-1041-LCV Herald 1200 Convertible

GA-8706-LCP Herald 1200 Coupe (Not imported into the U.S.A.)

GA-10331-LSC Herald 1200 Estate Car (Not imported into the U.S.A.)

permits adjustment of the rack, by adding or removing shims, without removing the unit from the vehicle.

Although the new steering unit is similar in appearance and may, as a complete assembly, be used to replace the earlier type fitted to original Herald Models, individual parts cannot be interchanged.

The Part Numbers affected are:

Rack and Pinion Steering	LHS 305051 replaced by 305459
Pinion Housing LH	LHS 304738 replaced by 208795

Plunger	128003 replaced by Plunger	120946
Shim	128810 replaced by Spring	126765
Plate Spring	128007 replaced by Screwed Cap	132053
End Cover	122129 replaced by Greased Plug	129242
Circlip	509536 replaced by Shim	132055
Grease Plug	128005 replaced by Shim	120959
	Shim	120949

W. T. Yeager
Zone Service Manager

W. T. Yeager
dm