

STANDARD-TRIUMPH MOTOR COMPANY, INC.



NORTHEASTERN ZONE

TO: All Dealers

BULLETIN: #T-61-33

DEPT: Service and Parts

DATE: November 27, 1961

SUBJECT: HERALD REAR HUB REMOVAL

Where it becomes necessary to apply any form of shock loading to facilitate the pulling of the rear hub from a Triumph Herald with the axle on the car, precaution should be taken to disconnect the axle shaft at the axle universal joint. This precaution will avoid possible damaging of the inner axle shaft during this operation.

W. T. Yeager
Zone/Service Manager

W. T. Yeager
dra