



TO: All Dealers

BULLETIN: #T-61-38

DEPT: Service and Parts

DATE: December 18, 1961

SUBJECT: TR-4 GAS LINE RATTLE

On certain TR-4s, the gas line rattles at the first attachment point from the gasoline tank. The bracket securing the pipe is fitted underneath the body directly above the rear shock absorber on the left hand side of the car.

This is being corrected in future production but where there is a loud, intermittent rattle from the left rear of the car, it is a simple matter to jack up the car, pull the gas line away from this bracket, insulate it with electrical tape or "Dum Dum" and snap it back into the bracket, ensuring that it is a snug fit.


ZONE SERVICE MANAGER

W. T. Yeager
dm