

STANDARD-TRIUMPH MOTOR COMPANY, INC.

NORTHEASTERN ZONE



TO: All Dealers

BULLETIN #T-61-6

DEPT: Service and Parts

DATE: May 11, 1961

SUBJECT: HERALD AXLE SHAFTS

Improvements in the material, machining and heat treatment of the Herald Axle Shaft makes it advisable that only the latest type should be used. We therefore require that you return to this Zone all stocks of the earliest type shaft, Part Number 124117, which is readily identifiable by the fact that it is not fitted with a steel flinger. Full credit or a new type axle will be issued.

W. T. Yeager
Zone Service Manager

W.T. Yeager
dm