

STANDARD-TRIUMPH MOTOR COMPANY, INC.

NORTHEASTERN ZONE



TO: All Dealers

BULLETIN: T-62-33

DEPT: Service & Parts

DATE: July 24, 1962

DISTRIBUTION: Distributors, Zone
Offices & Dealers

REF: S.I.S. 5/43

RELEASE: Immediate

SUBJECT: HERALD & TRIUMPH 1200
HOOD ASSEMBLY

From approximate Commission Numbers GA-55100, G-69180 restricter stays were fitted to the hoods of all Herald & 1200 models and, at the same time, the two stop brackets were deleted from the cross tube assembly, part number 205317.

Spares Division will keep supplies of the cross tube assembly fitted with the two stop brackets, 122358, for servicing earlier vehicles.

Lewis B. Thompson
Service Manager