

STANDARD-TRIUMPH MOTOR COMPANY, INC.

NORTHEASTERN ZONE



TO: All Dealers

BULLETIN: T-62-36

DEPT: Service & Parts

DATE: July 24, 1962

DISTRIBUTION: Distributors, Zone
Offices & Dealers

REF: S.I.S. 2/39

RELEASE: Immediate

SUBJECT: TRIUMPH TR-4
GEARBOX TOLERANCES

In Preliminary Service Information TR-4, an error exists in the paragraph giving the overall end float of 2nd and 3rd gear bush on mainshaft as .003" - .009".

These tolerances should be amended to read .033" - .017". This clearance is measured between the forward face of the flange of the 2nd speed bush and rear face of the 3rd speed gear when assembled to the mainshaft.

Lewis B. Hodgson.

Service Manager