

STANDARD TRIUMPH MOTOR COMPANY, INC.

NORTHEASTERN ZONE



TO: All Dealers

DEPT: Service & Parts

DISTRIBUTION: All Dealers

RELEASE: Immediate

BULLETIN: T-62-44

DATE: August 23, 1962

REF: EC/5653

SUBJECT: TRIUMPH TR-4
PROPELLER SHAFT

The grease fitting for the front universal joint spline on the Triumph TR-4 propeller shaft has been revised from a straight fitting to a 45° angle fitting to improve accessibility during lubrication.

Existing vehicles having the straight fitting should be modified in cases of difficulty of access to the grease fitting by substituting an Alemite fitting number 1637B.


Service Manager

lnc