

STANDARD-TRIUMPH MOTOR COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: PARTS AND SERVICE

BULLETIN T-63-44

SUBJECT: TRIUMPH 1200 CHASSIS FRAME

DATE: JUNE 28, 1963

As a result of rationalization of frame assemblies, the Spares Division will only supply a frame assembly (part numbers 401333 or 401862); or a front cross tube assembly (part number 205817).

When hood stays were introduced, the hood stop brackets were deleted from the front cross tube assembly (205817).

Refer to Service Bulletin T-62-42 when ordering a chassis frame or cross tube assembly for cars manufactured before the fitting of hood stays, two brackets, part number 122358, must be ordered also. The brackets must be welded to the cross tube as on the original assembly.

This information refers only to chassis frames up to commission number GA-80000. For chassis frame details after this number reference should be made to the Spare Parts Catalog.