

STANDARD-TRIUMPH MOTOR COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE AND PARTS

BULLETIN T-63-57

SUBJECT: SPITFIRE FRICTIONLESS
PROPELLOR SHAFTS

DATE: AUGUST 22, 1963

Under no circumstances must the sliding portion of the frictionless propeller shafts fitted to the Spitfire models be removed from the main member. (Part Numbers 209834 and 210508).

Should any of these shafts be inadvertently dismantled, they must be replaced by another unit as they can only be rebuilt by the manufacturers.

Any dismantled shafts returned cannot be treated as warranty procedure.