

STANDARD-TRIUMPH MOTOR COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE & PARTS

BULLETIN T-63-65

SUBJECT: CHASSIS FRAMES - HERALD

DATE: OCTOBER 25, 1963

It would seem that there is still some confusion as to the correct type of chassis frame to be used for the servicing of Herald Estate cars and convertibles, mark II condition - i.e. from commission number 80,000 and future.

The original mark I chassis frame for servicing these two vehicles was part number 401861, but with the introduction of the mark II condition all chassis frames for all Herald models became common. Therefore, each of these four types of Heralds i.e. Saloon, Estate Car, Convertible and Coupe, are serviced under part number 401987 - mark II condition.

Details are as follows:

Part No. 401333 Mark I - Saloon and Coupe up to Comm. No. 80,000
Part No. 401861 Mark I - Estate & Convertible up to Comm. No. 80,000
Part No. 401987 Mark II - For all Herald Models i.e. Saloon, Estate Car, Convertible & Coupe from 80,000 and future.

The new conditions of frame are shown on pages 29A and 29B of the main Herald 1200 Catalog, No. 510997, Second Edition. The Frame Condition 401974 will not now be used as it is replaced by 401987.

Will you please record this information to avoid any possibility of incorrect ordering in the future.