

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

BULLETIN T-66-26

SUBJECT: SPECIAL SAFETY CHECK
CAMPAIGN - BRAKE PIPE
FOR IMMEDIATE AND URGENT ACTION

DATE: APRIL 27, 1966

All Triumph 2000 cars sold through your organization should be called in immediately for the position of the brake pipes on the trailing arms to be examined to ensure that they have adequate clearance from the coil spring.

The correct and firm clipping of the brake pipe to the trailing arm should also be checked.


New unsold cars should be checked in a similar manner before release.

Pipes should be reset where the clearance is less than 1" and if damaged should be replaced.

An illustration showing the location of the pipe and the position of the clip is attached.

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



SA1/8

