

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

BULLETIN T-66-36

SUBJECT: INSPECTION OF DISC BRAKE PADS

DATE: JULY 9, 1966

Cases have occurred where unnecessary damage to brake discs has been caused by allowing the pads to wear excessively to a point where a metal to metal contact occurs.

It is strongly recommended that each routine servicing at 6,000 mile intervals a quick check be made of the progress of wear on the brake pads and if the lining material is found to be 1/3 or less than its original thickness, the owner should be advised that renewal will be necessary before the next service is due and thereby prevent the possibility of the discs becoming damaged in the meantime.