

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

BULLETIN T-66-42

SUBJECT: REAR BRAKE CYLINDERS
TR RANGE

DATE: AUGUST 11, 1966

The current rear brake cylinder part number 510942 supersedes the early type part number 504835 and does not contain a piston spring.

When the latest type is fitted in service, to one wheel, the cylinder of the opposite wheel should be checked to ascertain whether it contains a piston spring or not.

If a spring is fitted it should be removed and discarded so that both cylinders are similar.

It is detrimental to the braking efficiency to have dissimilar conditions of cylinder on the car.

As the time of checking the brake cylinder, it is recommended that the seals are renewed if the mileage is in excess of 36,000 miles.