

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

BULLETIN T-67-12

SUBJECT: GENERATORS AND CONTROL BOXES

DATE: FEBRUARY 16, 1967

In the course of an investigation into faulty control boxes returned under warranty, it was observed that a number of them have been readjusted in service. This destroys the evidence of the cause of the trouble.

If any fault is experienced with a control box on a car under warranty, it is recommended that the control box is exchanged for a new one.

Examination of generators recently returned under warranty revealed that some have failed because of a fault in the control box. Therefore, if an electrical fault in the generator is suspected, both the generator and control box must be renewed as a pair and returned under the same warranty claim form. This will avoid damage to the replacement dynamo because of a fault in the control box.