



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

BULLETIN T-67-5

SUBJECT: GT-6 BATTERY TERMINAL

DATE: JANUARY 26, 1967

---

Cases have occurred of a short circuit to ground between the positive battery terminal securing screw and the choke and heater control cables.

This situation arises usually in cases where the battery terminal securing screw has not been properly or fully seated. As an extra precaution, it is recommended that the choke cable and the heater control cable are encased in a locally procured PVC sleeve.

Recommended dimensions of the PVC sleeve are approximately 8" in length, 3/8" in diameter and 3/64" in thickness. Warranty claims will be accepted for this operation on the basis of 15 minutes labor, which includes the cost of the PVC material.

In carrying out this modification, or any other work involving electric connections, it is imperative that the safety precaution of always first disconnecting the negative battery lead be taken.

The necessary modification is being incorporated on production immediately.