

Confidential

TECHNICAL SERVICE BULLETIN

NO. 1.C.4



TRIUMPH

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

19101-41010

DATE: June 20, 1969

SUBJECT:

Soft Top

MODELS:

Spitfire MK III

Information Only

Instructions for lowering the soft top are given on page 14 of the Spitfire MK III Owner's Handbook, North American Edition (545073), a section of which reads as follows:-

"Push the soft top header rail rearwards and slightly upwards while knocking the second hoodstick (arrowed Fig. 15) forwards, until the assembly begins to fold. DO NOT PULL the second hoodstick downwards. Continue lowering the frame and pull the fabric flat over the luggage compartment lid (Fig. 18)."

Important

Dealers are reminded if the second hoodstick is pulled downwards it is possible for the flat ends of the stick to cut into and damage the hood fabric.

Please pass on this information to your dealership, personnel and owners.

HCT/kk