

Confidential

TECHNICAL SERVICE BULLETIN

1-D-3

NO.



TRIUMPH

DATE: 6-5-69

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

MAINSHAFT THRUST WASHERS


MODELS:

GT6+ & SPITFIRE MARK III

To provide greater scope when adjusting the end float of mainshaft gears on the Spitfire Mark III and GT6+, an additional thrust washer 149963 has been introduced.

The range of 2nd and 3rd mainshaft gear thrust washers is now:

111422	-	Thin
131843	-	Thick
149963	-	Intermediate



HCT: mmm