

TECHNICAL SERVICE BULLETIN

NO.

71-B-6



TRIUMPH

SUBJECT:

Distributor Contact Gap

MODELS:

Stag

Please note the Distributor Contact Gap clearance has been amended from 0.010" - 0.012" to 0.014" - 0.016". Consequently, the dwell angle has also changed from 34° - 37° to 29½° - 33½°. This new setting applies to all Triumph Stags.

The ignition timing of 11° BTDC static (5° ATDC at idle) remains unchanged.