

STANDARD-TRIUMPH MOTOR COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE AND PARTS

BULLETIN T-63-18

SUBJECT: TRIUMPH 1200 - FRONT SUSPENSION
VERTICAL LINKS

DATE: FEBRUARY 15, 1963

To assist standardization, the boss for locating the oil seal on the vertical link was increased from 1.380 (35 mm) to 1.500 (38 mm) at commission numbers:

GA-45683 (drum brakes)

GA-46960 (disc brakes)

The modified link can be identified by the embossed serial numbers 1 L0 2157 situated on the upper leg of the link. The earlier types were embossed with the serial number 1 L0 2129.

The two links are interchangeable with each other providing that the seal assembly, consisting of a felt seal and retainer is renewed at the same time.

The affected part numbers are:

Vertical Link RH 205483 replaced by 209222

Vertical Link LH 205484 replaced by 209223

Felt Seal 100867 replaced by 132668

Oil Seal Assembly 107194 replaced by 132664