

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

ATTN: SERVICE & PARTS

BULLETIN T-64-25

SUBJECT: SPITFIRE & 1200 PROPELLER SHAFTS

DATE: JULY 17. 1964

Bulletin T-63-57 gave information concerning servicing of frictionless propeller shafts.

Please note that the frictionless type of propeller shaft has now been deleted for the regular type from the following serial numbers:

Spitfire - FC-1876
1200 - GD-15853

Property of The Vintage Triumph Register
www.VTR.org