

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

BULLETIN T-66-28

SUBJECT: TRIUMPH 2000 INSTRUMENT CLUSTER

DATE: APRIL 28, 1966

In the event of an instrument failure, whether it be the amp meter, the fuel gauge or the temperature gauge, we have been advised by the instrument manufacturer that the whole unit is to be changed as a unit.

It is important, however, that when the faulty unit is returned for warranty exchange that the label clearly states which part of the unit is faulty, whether it be the fuel gauge, the temperature gauge or the amp meter. Under no circumstances is this instrument to be dismantled to correct any one of the separate units.

You are strongly advised to carry one of these units in stock to avoid a vehicle being kept off the road.

The part number of the instrument involved is 210630. The Smiths code number is IP.3226/00.