

LEYLAND-TRIUMPH SALES COMPANY, INC.

WESTERN ZONE



TO: ALL TRIUMPH DEALERS - WESTERN ZONE

DEPT: SERVICE DEPARTMENT

SUBJECT: CLAIMS ON GEARBOX AND REAR AXLE

BULLETIN T-67-3
(Re-issue of T-66-45)

DATE: JANUARY 19, 1967

This bulletin is to advise that all future warranty claims for repairs performed on gearboxes and rear axle units must show the serial number of the respective unit. This number should be typed in the far right hand column under "Description & Unit Invoice No." The serial number can be easily obtained while the unit is out of the automobile.

This also applies to automatic transmission repairs. Should you have to send a Triumph 2000 automatic transmission to a transmission shop for internal repairs, you should request them to obtain the serial number of the unit and advise this information when they bill you.

The reason behind this request is to enable the Quality Investigation Department to fully investigate the various complaints in the above units. Your cooperation will be appreciated to avoid the return of claims to you for information.