


TECHNICAL SERVICE BULLETIN

NO.

1-G-9

DATE: July 1970

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

STEERING COLUMN LOCKS

MODELS:

ALL MODELS

In the event that a claim is made in respect of any of our products alleging that accidental damage or personal injury has occurred as a result of a malfunction of the steering column lock it is imperative that the following action be taken:

1. Do not remove the lock from the car or exert unusual forces on the key.
2. Immediately contact your Distributor's Service Manager for further advice.

Removal of the lock or the exertion of unusual force on the key will destroy critical evidence and will make it impossible to ascertain whether, in fact, there was a malfunction of the lock.